This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

LUMIMAIRE INVENTOR: BARRY WHITE, et al. SN: 10/616,743; DOCKET NO.: 0331 ATTY: DONALD E. HASSE; PHONE: (513) 229-0383



LUMIMAIRE INVENTOR: BARRY WHITE, et al. SN: 10/616,743; DOCKET NO.: 0331

SN: 10/616,743; DOCKET NO.: 0331 ATTY: DONALD E. HASSE; PHONE: (513) 229-0383





FIG. 2


LUMIMAIRE

INVENTOR: BARRY WHITE, et al. SN: 10/616,743; DOCKET NO.: 0331

ATTY: DONALD E. HASSE; PHONE: (513) 229-0383

3/5





OUTSIDE REFLECTORS MATERIAL: ALANOD MIRO 4

FIG. 3

LUMIMAIRE INVENTOR: BARRY WHITE, et al.
SN: 10/616,743; DOCKET NO.: 0331
ATTY: DONALD E. HASSE; PHONE: (513) 229-0383




FIG. 4

LUMIMAIRE
INVENTOR: BARRY WHITE, et al.
SN: 10/616,743; DOCKET NO.: 0331
ATTY: DONALD E. HASSE; PHONE: (513) 229-0383




FIG. 5